



## Sato M8490Se Print Engine

Rebuilding Package which includes these Parts:

Assembly	Quantity	P/N	DESCRIPTION
Frame including Feed Roller	1	ILSPD1731300	DISPENCE BAR
	3	ILSPR0730100	PLATEN ROLLER
	3	ILSPB2730100	COLLAR
	3	ILSMJ1300424	W-POINT SCREW
	7	ILSPT1112060	BEARING INNER
	3	ILSPT1109050	SUPPORTER
	2	ILSPE8730200	PULLEY 24/36
	1	ILSPE8730500	PULLEY 24/36
	7	ILSND0040030	E-SNAP RING
	1	ILSPB0731600	ROLLER SHAFT
	3	ILSPR1730600	TENSION ROLLER
	1	ILSPT8165064	TIMING BELT
	1	ILSPR1733300	PULLEY
	3	ILSMJ1400524	HEX W-POINT SCREW
	1	ILSPT8074064	TIMING BELT
	3	ILSPT8150064	TIMING BELT 150MXL 6.4G
	1	ILSPL1720100	MOTOR PULLEY
	2	ILSPB0730600	POST
	2	ILSMD4400822	PAN HEAD SCREW
	1	ILSPB0731701	IDLE SHAFT
	1	ILSPE8730100	GEAR
1	ILSPE8730300	PULLEY	
Print Head	1	ILSPR0730200	RIBBON FEED ROLLER
	1	ILSPT1112060	BALL SUPPORTER
	1	ILSPT1109050	BALL SUPPORTER
	1	ILSPE8730100	GEAR
	1	ILSND0040030	E-CLIP
	1	ILSMD4300822	PAN HEAD SCREW
	1	ILSMC0401022	PAN HEAD SCREW
	2	ILSMD3250522	PAN HEAD SCREW
Pressure Roller	1	ILSPB0731800	PRESSURE ROLLER
	2	ILSPT1108040	BALL SUPPORTER
	4	ILSMJ9300622	THIN HEAD SCREW

**68 Parts replaced including Labor**

**Contact us for Pricing**

### Need to replace the Print Head?

Add as an option to the package above or purchase separately:



If purchasing separately please note that it is recommended that other parts be replaced when replacing the Print Head. Call for details.

### Does your printer use a Ribbon?

In addition to the list above we recommend replace these parts:

2 each	ILSPA0680300	FRICITION WASHER
2 each	ILSPR1730900	RIBBON BOSS
2 each	ILSPT2301020	OILESS WASHER
2 each	ILSPA0680400	DISC

**Contact us for Pricing.**

**As a Sato Distributor we can make available to you Sato's Full Product Line or any Spare Part. Browse [imisolutions.com](http://imisolutions.com) or give ILS a call.**